Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0105**

Resource Identification

Property Name(s): ..... House, Route 610 {Function/Location}
Property Date: 1870
Address(s): ..... Route 610 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior end	Brick	
Chimneys	Chimneys - Exterior end	Brick	
Porch	Porch - 1-story, 3-bay	Wood	Porch - Posts, Turned
Roof	Roof - Gable	Asphalt	Roof - Shingle
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 2/2

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1870 ca {VDHR Survey File}
Primary Resource? ..... Yes
Architectural Style: ..... Other
Interior Plan Type: ..... Central Passage, Single Pile
Accessed? .....
Number of Stories: 2.0
Condition: .....
Threats to Resource: .....

Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: I-house
End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Significance Statement: Late 19th century I-house with one exterior brick chimney and l one interior brick stove chimney.

Bibliographic Documentation

Ownership Information

Report generated 11/17/04

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: .... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-105
Negative no(s).

City/Town/Village/Hamlet: Windsor Vicinity
County: Isle of Wight
Street address or route number: Rte. 610, 1 mi. north of Rte. 609
U.S.G.S. Quad: Windsor
Historic name:
Common name:

Present use: Dwelling
Original use: Dwelling
Building Style: Vernacular
Building Date(s): late 19th century

1. Construction Materials

- [x] wood frame
- [ ] brick
  - bond: [ ] English [ ] Flemish [ ] ____-course American [ ] stretcher [ ] other ____
- [ ] stone
  - [ ] random rubble
  - [ ] coursed rubble
  - [ ] ashlar [ ] dressed [ ] rock-faced
- [ ] log:
  - [ ] squared [ ] unsquared
  - notching: [ ] V-notch [ ] saddle [ ] square [ ] half dovetail [ ] full dovetail [ ] diamond
- [ ] concrete block
- [ ] terra cotta
- [ ] steel frame
- [ ] other ____

2. Cladding Material

- [x] weatherboard
- [ ] vertical siding
- [ ] board & batten
- [ ] shingle: [ ] wood [ ] asbestos [ ] asphalt
- [ ] bricktex
- [ ] other ____
- [ ] composition siding
- [ ] stucco
- [ ] aluminum or vinyl siding
- [ ] cast iron
- [ ] sheet metal
- [ ] enameled metal
- [ ] glass



3. Stories (number): 2
   - [ ] low basement
   - [ ] raised basement

4. Bays (number): front 3 side (church) ____
   - [x] symmetrical
   - [ ] asymmetrical

5. Roof Type
   - [ ] shed [ ] parapet?
   - [x] gable [ ] pediment? [ ] parapet? [ ] clipped end? [ ] cross gable? [ ] central front gable?
   - [ ] hipped [ ] pyramidal?
   - [ ] mansard
   - [ ] false mansard
   - [ ] gambrel
   - [ ] flat [ ] parapet?
   - [ ] roof not visible
   - [ ] other ____

6. Roofing Material
   - [x] shingle
     - [x] composition (asphalt, asbestos, etc.)
     - [ ] wood
   - [ ] metal
     - [ ] standing seam
     - [ ] corrugated
     - [ ] pressed tin (simulated shingles)
   - [ ] tile
     - [ ] pantile [ ] flat [ ] glazed
   - [ ] slate
   - [ ] not visible

7. Dormers (number): front ____ side ____
   - [ ] gable [ ] pediment?
   - [ ] shed
   - [ ] hipped

8. Primary Porch
   - style ____
   - stories 1
   - levels 1 bays 3
   - materials wood, asphalt shingles
   - description and decorative details: Turned columns, hipped roof.

9. General supplementary description and decoration: Exterior brick chimney one end, interior brick stove chimney other end. Two-over-two sash. Unbeaded weatherboards.

10. Major additions and alterations:

11. Outbuildings:

12. Landscape Features:

13. Significance: Late 19th-century I house with one exterior brick chimney and one interior brick stove chimney.

Surveyed by: Willie Graham
Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey